## LEACHATE COLLECTION WELLS INTERIM OM&M MONITORING AND BAILING DATA SHEET WASTE DISPOSAL, INC. SUPERFUND SITE

| * |            | 73  | 2,44,6 |
|---|------------|-----|--------|
| D | Δ          | - 1 | 1-4    |
|   | <i>[</i> ] | . 1 | 1      |

August 17, 2006

TECHNICIAN NAME: Baltazar

TECHNICIAN SIGNATURE

| WELL | BOTTOM OF<br>WELL<br>AFTER<br>CONSTRUCT- | MEASURED<br>BOTTOM OF<br>WELL | 1     | GING<br>ME |                         | Ι           | EPTH T                  | O LIQUI<br>ft)          | D           |                         | LIQ<br>COL | HT OF<br>UID<br>UMN<br>ft)  | VOLUME<br>OF LIQUID | COMMENTS   |
|------|--|-------------------------------|-------|------------|-------------------------|-------------|-------------------------|-------------------------|-------------|-------------------------|------------|---|---------------------|------------|
| ID   | ED<br>[TOTAL                             | [TOTAL<br>DEPTH]              |       |            |                         | Start       |                         |                         | Finish      |                         |            | Arrest de la constitución de la | REMOVED (gallons)   | COMMISTATO |
|      | DEPTH]<br>(ft)                           | (ft)                          | Start | Finish     | 1 <sup>st</sup><br>Rdg. | 2nd<br>Rdg. | 3 <sup>rd</sup><br>Rdg. | 1 <sup>st</sup><br>Rdg. | 2nd<br>Rdg. | 3 <sup>rd</sup><br>Rdg. | Start      | Finish  |                     |            |
| LC-1 | 22.25                                    | 22.24                         | U541  | 0554       | 1982                    | 19.82       | 1982                    | 21.29                   | 21:29       | 21.29                   |            |   |                     |            |
| LC-2 | 21.90                                    | 21.90                         | 0600  | 06101      | <b>3</b> 1380           | 380         | 1380                    | 21.13                   | 21.13       | 21.13                   |            |   |                     |            |
| LC-3 | 22.20                                    |                               |       |            |                         |             | distriction             |                         |             |                         |            |   |                     |            |
| LC-4 | 21.90                                    | 21.90                         | 0618  | 0631       | 13.25                   | 1325        | 13.25                   | 21.15                   | 21.15       | 21.15                   |            |   |                     |            |

W:\Interim\_QM+M\LeachateCollectionWells\WorkPlan+FieldForms\August2006\Aug1706LC-WellsM&B(YF1).doc



## LEACHATE COLLECTION WELLS INTERIM OM&M INSPECTION SHEET WASTE DISPOSAL, INC. SUPERFUND SITE

| INSPECTOR'S NAME | INSPECTOR'S STONATURES | INSPECTION TIME | INSPECTION DATE |  |  |
|------------------|------------------------|-----------------|-----------------|--|--|
| Baltazarí        |                        | ,0200           | August 17, 2006 |  |  |

|  |                 | CONDITIONS      | OBSERVED        |                 |          | CHECK (•)            |
|--|-----------------|-----------------|-----------------|-----------------|----------|----------------------|
| ITEM OF POTENTIAL CONCERN                    | WELL ID<br>LC-1 | WELL ID<br>LC-2 | WELL ID<br>LC-3 | WELL ID<br>LC-4 | COMMENTS | BELOW WHEN COMPLETED |
| Wellhead (well box, cover, gasket, concrete) | OK              | 0/<             |                 | 014             |          |                      |
| Well Casing and Cap/Plug                     | 0<              | ok              |                 | 0               |          |                      |
| Liquid Present in Well Box                   | 40              | 10              |                 | 7               |          |                      |
| Other:                                       |                 |                 |                 |                 |          |                      |
| Other:                                       |                 |                 |                 |                 |          |                      |
| Other:                                       |                 |                 |                 |                 |          |                      |

 $W: \label{thm:condition} We in the condition when the condition of the conditions of the condition of the$ 



| DAILY F   | ELD REPORT  |           |                           |
|---|---|-----------|---------------------------|
| JOB NAME: WASTE DISPOSAL, INC. (WDI)  | PROJECT NUMBER: 290316-0                                    | )1/1001   | DATE: 8/17/2006           |
| LOCATION: Santa Fe Springs, California                                      | WEATHERONENCAS  | +         | DAY: Thursday             |
| INTERIM OM&M CONTRACTOR: TRC  | FOREMAN:  |           |                           |
| FIELD TECHNICIAN:  OUTO   SUMMARY OF OPERATIONS/WORK PERFORM                | INSPECTION/TESTING OF:<br>LEACHATE MONITORING/CON<br>RMED:: | TROL SYST | EM                        |
| Drived around 5 damage or trasi Bail SC-1, LC SSgallon drum. Casing of each | ite to chee - ganged o -2 and ic-i Cleaned t well.          | ide a     | For<br>pand<br>o q<br>and |
|   |   |           |                           |
|   |   | Custome   | r-Focused Solutions       |

Note: Specific System Data and Observations are Included on "Interim OM&M Inspection Sheets" and "Interim OM&M Monitoring and Bailing Data Sheets"

DAILY FIELD REPORT WASTE DISPOSAL, INC SANTA FE SPRINGS, CALIFORNIA

TRC

FIGURE J.1